UI Bulletin #123d

Subject:	Roof Beacon (TRW) Switch Wiring Location/Access
Models Years Affected:	2014-19 Chevrolet Silverado 1500 LD 2014-19 GMC Sierra 1500 LD 2015-19 Chevrolet Silverado 2500/3500 HD 2015-19 GMC Sierra 2500/3500 HD 2019 – beyond Chevrolet Silverado MD Trucks With option TRW
Origination Date:	February 6, 2015
Revision Date:	May 11, 2020

ADVISORY:

NOTE: This bulletin does not apply to the 2019 New Body Style models

Condition/Concern:

Customer and Upfitters may made several inquiries in search of the location and access methods for the blunt cut wiring for the Roof Beacon provision option (TRW). NOTE: Blunt cut wires are only ~ 2 inches in length.

Repair/Recommendation:

The following illustration are intended to provide information on wire locations and how to remove the center panel/section of the Overhead Console to gain access to the provided blunt cut wires.


2" Blunt Cut wires for Roof Beacon are tucked up above the Over-head Roof Console (green w/blue tracer and a solid black wire image on next page)
1

Roof Console Removal

To access the blunt cut wires for the roof beacon, remove center section of the Roof Console as follows…

1. Use a flat bladed plastic trim tool in order to release the retainer clips securing the trim plate to the roof console assembly.

2. Disconnect electrical connections where/when required.

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.

UI Bulletin #123d

Top View of Removed Overhead Roof Console



Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.

UI Bulletin #123d

Roof Beacon (TRW) Provision Schematic:



Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.